567 E. Hudson St. Columbus, OH 43211 614/298-2000

## **OHIO HISTORIC INVENTORY**

RPR Number:

1. No. <b>LOR-1929-21</b>	4. Present Name(	s)		] 2 5
2. County <b>Lorain</b>	5. Historic or Oth	Other Name(s) Sperry House		LOR-1929 2. County -21 Lorain
6. Specific Address or Location 50 West Vine		19a. Design Sources	35. Plan Shape <b>Square</b>	
		20. Contractor or Builder	36. Changes associated with 17/17b Dates:	
6a. Lot, Section or VMD Number 0900085112043		21. Building Type or Plan Other House Type 22. Original Use, if apparent Single Dwelling	17. Original/Most significant construct  17b.	
7. City or Village				
Oberlin			37. Window Type(s) 1 over 1	4.
9. U.T.M. Reference Quadrangle Name: Oberlin 17 397875 4571340		23. Present Use Single Dwelling	38. Building Dimensions 39' x 28'	resent or
Zone Easting Northing  10. Classification: <b>Building</b>		24. Ownership <b>Private</b> 25. Owner's Name & Address, if known	39. Endangered? NO By What?	riesent of mistoric Name(s
11. On National Register? <b>NO</b>			40. Chimney Placement	- Inie(s)
13. Part of Established Hist. Dist? NO 15. Other Designation (NR or Local)		26. Property Acreage <b>0.11</b>	Center	_
		27. Other Surveys	41. Distance from & Frontage on Road <b>35' approx</b>	
		28. No. of Stories Two story	51. Condition of Property:  Excellent	
16. Thematic Associations: Public Spaces College Grocery		29. Basement? Yes 30. Foundation Material Stone bearing	52. Historic Outbuildings & Dependencies Structure Type	
17. Date(s) or Period 17. <b>c. 1896</b> 18. Style Class and Design	b. Alteration Date(s)	31. Wall Construction  Balloon/western/platform frame	Date	
Dominant Dutch Colonial Revival		32. Roof Type  Gambrel  Roof Material	Associated Activity	
18a. Style of Addition or Elements(s)		Asphalt shingle  33. No. of Bays 2 Side Bays 3	53. Affiliated Inventory Numbers	-
19. Architect or Engineer		34. Exterior Wall Material(s)	Historic (OHI)	
		Wood shingle	Archaeological (OAI)	1
		l		₩

This Dutch Colonial Revival house features a recessed porch at the right corner of its main/south facade. Within the porch, the wood door has a large, oval window. A leaded & beveled glass window is right of the door. The porch has square pilasters & square columns supporting it. Left of the porch, a large 1/1 window has an upper sash that is smaller than the lower sash. Another square pilaster is located at the far left corner of the house. The second story features the gambrel gable indicative of Dutch Colonial Revival style. The gable extends to just above the 1st story & its wood shingles bow out at the 1st story. 2 1/1 double hung windows at the 2nd story have segmental arched pediments above the windows with a torch & laurel wreath design at the center of each arch. The arches have cornice returns. The attic has a pair of windows that form 1 arch with a wood 'keystone' at the top. The east elevation features a door at the center, below a projecting bay, which is supported by decorative brackets. A small window left of the door has muntins that form diamonds. The projecting bay has small, sawtooth shingles at the lowest row & features a pair of 1/1 double continued...

43. History and Significance (Continue on Reverse if necessary)

In 1896, the 'Gentleman Explorer' Dr. Lyman B. Sperry led a team to an unexplored glacier in what would become Glacier National Park. The glacier is known today as Sperry Glacier, and it rests on Mt. Oberlin. Also in 1896, some two thousand miles away in Oberlin, Ohio, on a parcel of land at the northwest corner of South Professor and West Vine, this house was moved to come to front on W. Vine. Dr. Lyman B. Sperry owned that parcel of land, and became, with his wife Rosa H., the first resident to live at 50 W. Vine. Sperry taught at Oberlin College and did much more traveling in his life, and, in fact, died in Glacier National Park. Lyman and Rosa Sperry moved out of this house, though, around 1908, making way for another Sperry family (but of no apparent relation), Merritt D., his wife continued...

This house is located on a residential street.

Oberlin City Directories. Oberlin News; 'Plans for property W. Vine and S. Professor', 06/19/1896, p. 5, c. 4; 'Died in Glacier Park; to be buried in Oberlin; obituary', 07/05/1923, p. 1, c. 6; 'To open grocery store', 02/25/1908, p. 1, c. 6; 'died; obituary', 06/30/1915, p.1, c. 7.; Oberlin College Archives Online. 'Louis D. Hartson, Biography'. <a href="http://www.oberlin.edu/archive/holdings/finding/RG30/SG12/adminhist.html">http://www.oberlin.edu/archive/holdings/finding/RG30/SG12/adminhist.html</a> Accessed 08/02/2005.; Blodgett, Geoffrey, 'Oberlin Architecture, College and continued...

<sup>42.</sup> Further Description of Important Interior and Exterior Features (Continued on Reverse if Necessary)

<sup>44.</sup> Description of Environment and Outbuildings (See #52)

<sup>45.</sup> Sources of Information

1. No. LOR-1929-21		4. Present Name(s)		
2. Cou	unty Lorain	5. Historic or Other Name(s) Sperry House		OR-1929 21
8. Site	Plan with North Arrow	54. Farmstead Plan :		1
	essor I		Door Selection: Single off center	
	W. Vine N↑		Door Position: Recessed	
			Orientation:  Gable end axis	
			Symmetry: Bilateral asymmetry	
Repor	rt Associated With Project:			
NADI	3#:			





1. No. LOR-1929-21	4. Present Name(s)	-21 FQR
2. County <b>Lorain</b>	5. Historic or Other Name(s) Sperry House	1929

42. Further Description of Important Interior and Exterior Features (Con't)

hung windows. The right side of the elevation has steps that lead to another door. Both doors have a window in the upper half & 3 filled wood panels below. A window is located between the doors. 1/1 double hung windows are located in the 2nd story to the left & right of the projecting bay. Another gambrel gable dominates this elevation & west elevation since the roof is a cross gable. The west elevation has a large 1/1 window with a small upper sash at the left side of the elevation. The right side has a bay window with a narrow 1/1 window that faces southwest (another likely faces northwest, but is not visible). The center window is leaded & has beveled glass. The bay has an entablature with dentil molding, frieze panels, & cornice. The 2nd story has 3 1/1 double hung windows. The attic has a pair of 6/1 double hung windows.

43. History and Significance (Con't)

Myrtle V., and their daughter Margaret E., an Oberlin College student. Merritt and family had lived in Piqua, Ohio for five years previous to moving into this house. Before that, they had lived in Oberlin. Sperry returned to take over the Sperry Grocery business from his brother. Myrtle died in 1915. Sometime between 1916 and 1920, Merritt Sperry moved out. Jean P. Youtz, a Conservatory student, lived here in 1920. The house maintained this college tie with the next known resident, Mary Agnes Stocker in 1927, who boarded students, and the house became known as Rose Cottage. This house is listed vacant in 1933. In 1935, the Phelps family moved in: Mrs. J.H.; Dorothy Turner, a student; Joel H., a student; Majorie, a student; and Vesta, a student. This house was once again vacant from 1937 to 1940 when Lewis D. Hartson, a professor in the Oberlin College Department of Psychology, wife Mary, and children Dorothy Helen, Robert Reed, and Mary Elizabeth moved in. Lewis compiled and edited the 1960 Oberlin Alumni Register, an 888-page source listing Oberlin College students. From 1943 to 1970, a large number of residents occupied this house including, in succession: Mrs. Ama Selover; F. Lugt; Charles E. Weltzheimer, wife Margaret B., and three children; D.M. Henderson and wife, Kathy G.; Hattie Selover; and James and Shirley Billingsly. It is worth note that Charles E. and Margaret B. Weltzheimer commissioned architect Frank Lloyd Wright to build a home at 127 Woodland. In the 1970s and 80s, it is unclear who lived at this house. The house was owned by David Breitman and Kathryn Stuart in the late 1990s - early 2000s. They undertook exterior renovations.

44. Description of Environment and Outbuildings (Con't)

45. Sources (Con't)

Town: A Guide to Social History,' Oberlin College, 1985.; City Directories, O.H.I.O Resource Center.; Holsworth, Pat, Oberlin Pioneer Database.; Sanborn Fire Insurance Maps.; Gordon, Stephen C., 'How to Complete the Ohio Historic Inventory,' Ohio Historical Society, Columbus. 1992.; McAlester, Virginia and Lee. 'A Field Guide to American Houses.' Alfred K. Knopf Inc. New York. 2000.; 'Alumni Register: Graduates and Former Students, Teaching and Administrative Staff, (1833-1960).' Oberlin College, 1961.; Lorain County Court House, Auditor Property Record, Internet, http://www.loraincounty.com/auditor/index.shtml, Accessed 2005.